

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P. O. Box 420, Farmington, NM 87499-0420	Telephone No.	(505)325-1821
Facility Name	Big Field #9	Facility Type	

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	NM-15654
---------------	---------	---------------	---------	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	15	30N	14W	1960	South	660	West	San Juan

Latitude 36.81222 Longitude 108.30277

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	approx 500 bbls	Volume Recovered	approx 400 bbls
Source of Release	Pit overflowed	Date and Hour of Occurrence	9/19/07 @ approx 10:00 a.m.	Date and Hour of Discovery	9/19/07 @ approx 1:30 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Aztec Office NMOCD – Brandon Powell & BLM Farmington Office – Erinn Shirley		
By Whom?	Rodger Mullins	Date and Hour	9/20/07 @ approx	@ approx 12:00 a.m.	
Was a Watercourse Reached?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	RCVD SEP 24 '07		
If a Watercourse was Impacted, Describe Fully.*	Went approximately 300 yards down wash			OIL CONS. DIV. DIST. 3	
Describe Cause of Problem and Remedial Action Taken.* Pop off valve broke on charge pump & overflowed pit. Spread urea on contaminated area. Contaminated soils tested by Blagg Engineering – awaiting results.					
Describe Area Affected and Cleanup Action Taken.* Location and wash contaminated. Spread urea on contaminated area. Contaminated soils tested by Blagg Engineering – awaiting results..					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Rodger Mullins		Approved by District Supervisor:  For: Charlie Perrier			
Title: Production Foreman		Approval Date: 9-24-07		Expiration Date:	
E-mail Address:		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: September 21, 2007 Phone: (505)325-1821					

* Attach Additional Sheets If Necessary

NBP0730452731