

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Lance Oil & Gas, Inc.	Contact	Jo Becksted
Address	P. O. Box 70, Kirtland, NM 87417	Telephone No.	(505) 598-5601 Ext. 5558
Facility Name	WF Federal 11 #1	Facility Type	Gas Well

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NMNM102886
---------------	-----	---------------	-----	-----------	------------

API #30-045-32268

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	11	30N	14W	1740'	South	670'	East	San Juan

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE



Type of Release	Produced Water	Volume of Release	10 bbls	Volume Recovered	7 bbls
Source of Release	Polish rod	Date and Hour of Occurrence	6/28/06 at approx. 12:00 a.m.	Date and Hour of Discovery	6/28/06 at 8:40 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	Jo Becksted of Lance Oil & Gas Company, Inc.	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\* Polish rod liner got stuck, leaked produced water.

Describe Area Affected and Cleanup Action Taken.\* The soil immediately surrounding the polish rod was impacted, however the water was contained on the wellsite. The polish rod was repaired, a water truck was dispatched to suck up puddled water, and the remaining soil was raked and graded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Jo Becksted		Approved by District Supervisor:  For: Charlie Perrin	
Title: Production Tech		Approval Date: 6/29/06	Expiration Date:
E-mail Address: jbeckste@westerngas.com		Conditions of Approval:	
Date: Phone: (505) 598-5601 Ext. 5558		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

nBPO619454283