

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RCVD DEC 12 '06
OIL CON. DIV.
Form C-141
Revised October 10, 2003
DIST. 3
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Lance Oil & Gas, Inc.	Contact Jo Becksted
Address P. O. Box 70, Kirtland, NM 87417	Telephone No. (505) 598-5601 Ext. 5558
Facility Name Salty Dog #4 SWD	Facility Type Salt Water Disposal Well
API #30-045-32334	

Surface Owner Bureau of Land Management	Mineral Owner Bureau of Land Management	Lease No. NMNM-101552
---	---	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	1	30N	14W	2580	South	1890	West	San Juan

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release ~100 bbls	Volume Recovered 0
Source of Release Open Valve on North Battery Tank	Date and Hour of Occurrence 12-06-06 @ ~ 1:30 a.m.	Date and Hour of Discovery 12-06-06 @ 1:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Kelly & Val Jamison of the BLM, Brandon Powell of the NMOCD	
By Whom? Jo Becksted	Date and Hour 12-6-06 @ 8:00 a.m.	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 100 bbls	



If a Watercourse was Impacted, Describe Fully.* Produced water traveled approximately 1 mile down a deep and narrow ravine and absorbed into the ground.

Describe Cause of Problem and Remedial Action Taken.* A valve was found in the open position due to suspected vandalism. When vessel "high-tanked", produced water was released through the open valve. Immediately upon discovery, valve was closed.

Describe Area Affected and Cleanup Action Taken.*

Val Jamison of the Bureau of Land Management and Brandon Powell of the New Mexico Oil Conservation Division inspected the impacted area and they concluded that no cleanup action was necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jo Becksted	Approved by District Supervisor:  For: Charlie Perrin	
Title: Production Tech	Approval Date: 12-12-06	Expiration Date:
E-mail Address: jo.becksted@anadarko.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: _____ Phone: (505) 598-5601 Ext. 5558		

* Attach Additional Sheets If Necessary

nBP0701738523