



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS
AND NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://dormrd.state.nm.us/ondoff/istrict/111301-111310.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test Nov. 30, 2009 Operator Maralex Resources API #30-0 45-34003

Property Name Dome Federal Well No. 1 Location: Unit Section 7 Township 27 Range 13

Well Status (Shut-In or Producing) Initial PSI. Tubing 76 Intermediate Casing 96 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min	0		96		
10 min					
15 min					
20 min					
25 min					
30 min	0		96		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 76

REMARKS

By Peter Jee
Lease Operator
(Signature)

Witness

E-mail address

