

District I - (505) 393-6161  
P.O. Box 1940  
Hobbs, NM 88241-1980  
District II - (505) 748-1283  
811 South First  
Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Road  
Aztec, NM 87410  
District IV - (505) 827-7131

**State of New Mexico**  
**Energy Minerals and Natural Resources Department**  
**Oil Conservation Division**  
2040 South Pacheco Street  
Santa Fe, New Mexico 87505  
(505) 827-7131

Form C-141  
Originated 2/13/97

Submit 2 copies to:  
Appropriate District  
Office in accordance  
with Rule 116.

Release Notification and Corrective Action

30 039 07684

**OPERATOR**

☐ Initial Report ☒ Final Report

Name:	Burlington Resources	Contact:	Ed Hasely
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9841
Facility Name:	SAN JUAN 29-7 UNIT 88	Facility Type:	Gas Well

Surface Owner:	Federal	Mineral Owner:	Federal	Lease Number:	NMSF-078943
----------------	---------	----------------	---------	---------------	-------------

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: Rio Arriba
N	06	029N	007W	990	South	1000	West	

**NATURE OF RELEASE**

Type of Release:	Condensate	Volume of Release:	6 BBLS.	Volume Recovered:	0 BBLS.
Source of Release:	Condensate Tank	Date and Hour of Occurrence:	3/22/2001	Date and Hour of Discovery:	3/22/2001
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?			
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA



Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

The load line valve on the condensate tank developed a small leak. The condensate dripped out into the bermed area. The leaking valve was replaced.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All fluids were contained inside the bermed area. The impacted soils were raked to promote remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>E. Hasely</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Ed Hasely	Approved by:	<i>Denny Faint</i>
Title: Environmental Representative		District Supervisor:	<i>For Frank Chavez</i>
Date: 3/22/01	Phone: (505) 326-9841 or 326-9842	Approval Date:	03/27/2001
		Expiration Date:	
		Conditions of Approval:	Attached: <input type="checkbox"/>

NDGF 010865-0909