


District I
1625 N French Dr , Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505



Form C-141
Revised March 17, 1999
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

30 039 25765

OPERATOR

☐ Initial Report -X ☐ Final Report-X

Name of Company Mallon Oil Company	Contact Ron Sansoni
Address P.O. Box 2797 Durango, CO 81302	Telephone No. (970) 382-9100
Facility Name Jicarilla 464-29 No. 9	Facility Type Gas Well

Surface Owner Jicarilla Apache Tribe	Mineral Owner Jicarilla Apache Tribe	Lease No. Jic 464
---	---	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 29	Township 30N	Range 03W	Feet from the 2430'	North/South Line FNL	Feet from the 2405'	East/West Line FEL	County Rio Arriba
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	----------------------

NATURE OF RELEASE

Type of Release Production Water	Volume of Release Est 20 bbls	Volume Recovered 10 bbls
Source of Release Production Tank	Date and Hour of Occurrence 02/09/01 AM	Date and Hour of Discovery 02/09/01 9:30 AM
Was Immediate Notice Given? Yes <input type="checkbox"/> No <input type="checkbox"/> <input checked="" type="checkbox"/> X Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> X	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully *

N/A

Describe Cause of Problem and Remedial Action Taken *

Water haul trucks forgot to haul , allowing tank to overflow Approximately 10 BW escaped from tank berm on low side Used vacuum tank to clean up water

Describe Area Affected and Cleanup Action Taken *

Affected area was inside of dyke and 10' x 20' outside of berm Rebuild dyke and spread dirt, then raked out.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature. <i>Ron Sansoni</i>	OIL CONSERVATION DIVISION		
Printed Name: Ron Sansoni	Approved by <i>Denny Faurt</i> District Supervisor. <i>for Frank Chavez</i>		
Title: District Production Superintendent	Approval Date: <i>2/15/01</i>	Expiration Date	
Date 02/13/01	Phone (970) 382-9100	Conditions of Approval	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGF 0104650015