

District I
1625 N French Dr, Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 25947

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company Mallon Oil Company	Contact Ron Sansoni
Address P.O. Box 2797 Durango, CO 81302	Telephone No. (970) 382-9100
Facility Name Jicarilla 458-5 No. 5	Facility Type Gas Well

Surface Owner Jicarilla Apache Tribe	Mineral Owner Jicarilla Apache Tribe	Lease No. Jicarilla 458
---	---	----------------------------

LOCATION OF RELEASE

Unit Letter H	Section 05	Township 30N	Range 03W	Feet from the 1640'	North/South Line FNL	Feet from the 790'	East/West Line FEL	County Rio Arriba
------------------	---------------	-----------------	--------------	------------------------	-------------------------	-----------------------	-----------------------	----------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 70	Volume Recovered 70
Source of Release Production Tank	Date and Hour of Occurrence 01/06/01 06:15 AM	Date and Hour of Discovery 01/06/01 6 15 AM
Was Immediate Notice Given? X Yes No <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Not Required	If YES, To Whom? Aztec O.C.D. - Denny Foust	
By Whom? Jimmy Costalez	Date and Hour 01/08/01 5:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> X No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken * Equalizer valve was left closed that allows the tank to hold more water and primary tank ran over into containment area surrounding the tank. Dawn Trucking vacuum tank sucked 70 barrels of water out of containment area.		
Describe Area Affected and Cleanup Action Taken.* Water did not escape from the containment area as much water as was possible was removed from containment area		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>RSansoni</i>	OIL CONSERVATION DIVISION	
Printed Name Ron Sansoni	Approved by <i>Denny Foust</i> District Supervisor <i>for Frank Chavez</i>	
Title District Production Superintendent	Approval Date: <i>01/24/01</i>	Expiration Date:
Date 01/18/01 Phone (970) 382-9100	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

N DG-F0100 955815

