


District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505



Form C-141  
Revised March 17, 1999

Submit copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

30039 26234

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company Mallon Oil Company	Contact Ron Sansoni
Address P.O. Box 2797 Durango, CO 81302	Telephone No. (970) 382-9100
Facility Name Jicarilla 464 SJ No. 8	Facility Type Gas Well

Surface Owner Jicarilla Apache Tribe	Mineral Owner Jicarilla Apache Tribe	Lease No. 464
---	---	------------------

LOCATION OF RELEASE

Unit Letter K	Section 29	Township 30N	Range 03W	Feet from the 1844'	North/South Line FSL	Feet from the 1345'	East/West Line FWL	County Rio Arriba
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	----------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Calculated 17 bbls	Volume Recovered 12 bbls
Source of Release Production Tank	Date and Hour of Occurrence 01/22/01 10:30 AM	Date and Hour of Discovery 01/22/01 10:30 AM
Was Immediate Notice Given? Yes <input type="checkbox"/> No <input type="checkbox"/> <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> X	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*

Load line valve on tank froze and broke creating spill Replaced broken valve with a new valve

Describe Area Affected and Cleanup Action Taken \*

Spill was contained in containment berm A vacuum truck was used for clean-up

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature. <i>Ron Sansoni</i>	Approved by <i>Jerry Teut</i> District Supervisor: <i>for Frank Chavez</i>	
Printed Name: Ron Sansoni <i>Ron Sansoni</i>	Approval Date: <i>2/14/01</i>	Expiration Date:
Title District Production Superintendent	Conditions of Approval.	
Date 02/09/01 Phone (970) 382-9100	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

NDGF 0104539727