


District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

30 039 26382

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Williams Field Services	Contact: Mark J. Baretta
Address: 188 CR 4900 Bloomfield, NM 87401	Telephone No. (505) 632-4634
Facility Name: Rosa # 184A	Facility Type: Well Site

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 34	Township 31-N	Range 5-W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
------------------	---------------	------------------	--------------	---------------	------------------	---------------	----------------	--------------------

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 50 bbls	Volume Recovered: 0 bbl
Source of Release: Reserve pit	Date and Hour of Occurrence: Monday, 9/17/01	Date and Hour of Discovery Monday, 14:35 PM 9/17/01
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? Mark Baretta	Date and Hour Monday, 16:00 PM 9/17/21	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

An evaporator spray head was poorly aimed and impacted the pit wall resulting in erosion of the wall and releasing approximately 50 bbls of produced water off site. The contractor in charge of the evaporation system was directed to properly place the equipment in the future.

Describe Area Affected and Cleanup Action Taken.*

The produced water flowed in a sheet flow manner down a slight grade for a distance of approximately 150 feet. It did not reach a watercourse. There was only slight staining of the soil, and samples were taken for analysis of hydrocarbon content.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Mark J. Baretta	Approved by District Supervisor: for Frank Chavez	
Title: Senior Environmental Specialist	Approval Date: 09/13/01	Expiration Date:
Date: 9/21/2001 Phone: (505) 632-4634	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

N DG-F 0126 057499