

District I
1625 N French Dr, Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised March 17, 1999

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BP	Contact Brittany Benko	
Address 200 Energy Court, Farmington, NM 87401	Telephone No. (505) 326-9235	
Facility Name Gallegos Canyon Unit 306	Facility Type Salt Water Disposal Facility	
Surface Owner Private	Mineral Owner Private	Lease No.

LOCATION OF RELEASE

Unit Letter I	Section 19	Township 29N	Range 12W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	---------------------------

NATURE OF RELEASE

Type of Release No release to the environment - FIRE	Volume of Release 0 bbls	Volume Recovered NA
Source of Release NA	Date and Hour of Occurrence 07/10/2001 3:50 pm	Date and Hour of Discovery 07/10/2001 4:08 pm (reported to BP)
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* At approximately 3:50 pm on July 10, 2001, the Gallegos Canyon Unit #306 was struck by lightning. The lightning ignited the oil sales tank and the gunbarrel. Heat from the fire also damaged the settling tank. The fire was put out by the Farmington City Fire Department using foam. No injuries or releases to the environment occurred.		
Describe Area Affected and Cleanup Action Taken.* A 300 bbl steel oil tank, 400 bbl fiberglass gun barrel, 400 bbl fiberglass settling tank and some miscellaneous piping and wiring were damaged.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Brittany D Benko	OIL CONSERVATION DIVISION Denny Fount	
Printed Name: Brittany D. Benko	Approved by District Supervisor: for Frank Chavez	
Title: Field Environmental Coordinator	Approval Date: 7/31/01	Expiration Date:
Date: 07/20/2001 Phone: 326-9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

ND 6502148716