

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division


2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.



Release Notification and Corrective Action

30045 25923

OPERATOR

☐ Initial Report

☒ Final Report

Name: Burlington Resources	Contact: GREGG WURTZ
Address: P.O. Box 4289 Farmington NM 87499	Telephone No.:
Facility Name: MCGRATH SWD 4	Facility Type: SWD

Surface Owner: Fee	Mineral Owner: Fee	Lease Number:
--------------------	--------------------	---------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
	34	30N	12W	800	north	1730	east	

NATURE OF RELEASE

Type of Release: Pre-injection produced water	Volume of Release: 15 BBLs.	Volume Recovered: 10 BBLs.
Source of Release: Storage tank	Date and Hour of Occurrence: 12/16/2001 8:00:00 AM	Date and Hour of Discovery: 12/16/2001 8:00:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom? DENNY FOUST	
By Whom? Gregg Wurtz	Date and Hour: 12/17/2001 8:00:00 A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0	

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Water from tubing coming out of well during snubbing and repair of well tubing. Free liquid was recovered. Impacted soil and gravel soil was removed and sent for remediation at Tierra Landfarm.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All liquid contained on location. Area affected was adjacent to tank storage area north and west of well head

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name: Gregg Wurtz	Approved by: <i>Denny Foust</i>	District Supervisor: <i>for Frank Chavez</i>
Title: Environmental Representative	Approval Date: 12/26/01	Expiration Date:
Date: Phone: (505) 326-9841 or 326-9842	Conditions of Approval:	Attached: <input type="checkbox"/>

11 DGF 0135556161