

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 26872

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Yates Petroleum Corporation	Contact	David Haggith
Address	105 South Fourth Street Artesia, NM 88210	Telephone No.	(505) 748-4223
Facility Name	Farnsworth Gas Unit B #1-E	Facility Type	Producing Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	8	30N	13W	1040'	North	960'	East	San Juan

NATURE OF RELEASE

Type of Release	Condensate/Produced Water	Volume of Release	57 bbls Oil 25 bbls Water	Volume Recovered	0 bbls Oil 0 bbls Water
Source of Release	Tank drain valve failure	Date and Hour of Occurrence	01/14/01 time unknown	Date and Hour of Discovery	01/15/01 4:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Steve Haden, OCD Farmington		
By Whom?	David Haggith	Date and Hour	01/16/01 3:50 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Drain valve on back of tank froze and broke. Valve replaced. Contracting with a third party environmental firm to conduct site investigation and remediation if necessary.

Describe Area Affected and Cleanup Action Taken.*

An area approximately 20' x 20' x 30" was affected by the release. Contaminated soil will be excavated and remediated in an on site land farm if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: David Haggith	Approved by District Supervisor:  for Frank Chavez	
Title: Environmental Coordinator, New Mexico	Approval Date: 1/26/01	Expiration Date:
Date: January 22, 2001	Phone: (505) 748-4223	Conditions of Approval: Submit Final
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary NMOCD 0101751565 spill report with results of soil excavation