

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

## State of New Mexico

## Energy Minerals and Natural Resources Department

## Oil Conservation Division

2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141  
Originated 2/13/97Submit 2 copies to:  
Appropriate District  
Office in accordance  
with Rule 116.

## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report☒ Final Report

Name: <u>30,045-27622</u> Burlington Resources	Contact: Ed Hasely
Address: P.O. Box 4289 Farmington NM 87499	Telephone No.: (505) 326-9841
Facility Name: LEWIS PARK 101	Facility Type: Gas Well

Surface Owner: Federal	Mineral Owner: Federal	Lease Number: NMNM-82815
------------------------	------------------------	--------------------------

## LOCATION OF RELEASE

Unit Letter M	Section 13	Township 031N	Range 008W	Feet From the 975	North/South Line South	Feet From the 870	East/West Line West	County: San Juan
------------------	---------------	------------------	---------------	----------------------	---------------------------	----------------------	------------------------	------------------

## NATURE OF RELEASE

Type of Release: Produced Water and Compressor Oil	Volume of Release: 16 BBLS.	Volume Recovered: 11 BBLS.
Source of Release: Compressor Scrubber Dump Tank	Date and Hour of Occurrence: 3/22/2001	Date and Hour of Discovery 3/22/2001
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

The fuel gas system on the separator plugged therefore the separator could not dump. The coal seam produced water carried over to the compressor and out the scrubber pot to a fiberglass tank. The open top tank overflowed onto the area around the tank and compressor. Released approximately 1 bbl of compressor oil and 15 bbls of produced water.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

The fluids were contained on location near the compressor and scrubber dump tank. Approximately 10 bbls of produced water and all the oil were recovered. The impacted area will be raked after the area dries.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Ed Hasely</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Ed Hasely</u>	Approved by: <u>Denny Fount</u>	District Supervisor: <u>for Frank Chavez</u>
Title: Environmental Representative	Approval Date: <u>03/27/01</u>	Expiration Date:
Date: <u>3/23/01</u> Phone: (505) 326-9841 or <u>326-9842</u>	Conditions of Approval:	Attached: <input type="checkbox"/>

N D G F 010 8680482