

State of New Mexico
Energy Minerals and Natural Resources Department

Oil Conservation Division
 2040 South Pacheco Street
 Santa Fe, New Mexico 87505
 (505) 827-7131

Submit 2 copies to
 Appropriate District
 Office in accordance
 with Rull 116 on
 back side of form

Release Notification and Corrective Action

30 045 28017

Name Phillips Petroleum Company		Contact Patsy Clugston
Address 5525 Hwy. 64, Farmington, New Mexico 87401		Telephone Number (505) 599-3454
Facility Name San Juan 32-8 Unit #225		Facility Type Gas Well



Initial Report



Final Report

Surface Owner Bureau of Land Management	Mineral Owner Federal	Lease No API # 30-045-28017
---	---------------------------------	---------------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 15	Township 31N	Range 8W	Feet from the 970	North/South Line South	Feet from the 1063	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	--------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release est. 55 bbls	Volume Recovered 50 BBLs
Source of Release Open valve	Date & Hour of Occurrence 10/15/2001	Date & Hour of Discovery 1430 hrs 10/16/01
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - by tele-fax	
By Whom? Patsy Clugston	Date and Hour 10/17/2001 0800 hrs	
Was a Watercourse Reached? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO water did not leave the tank berm	If YES, Volume Impacting the Watercourse no spilled water impacted a watercourse	
If a Watercourse was impacted, describe fully (Attach additional sheets if necessary) na		

Describe cause of problem and remedial action taken (attach additional sheets if necessary)

Water was discovered inside the eathern berm around the tank storage. Water Hauler left the valve in the open position after taking a load of produced water .
No water left the diked area around tank or the lease.

Describe area affected and cleanup action taken Attach additional sheets if necessary)

Estimated 55 bbls water spilled and 50 bbls sucked up and disposed of properly.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the Operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature original signed by Patsy Clugston & faxed 10/17/01	OIL CONSERVATION DIVISION	
Printed Name Patsy Clugston	Approved by <i>Denny J. Chavez</i> District Supervisor	Expiration Date 11/16/01
Title Sr. Regulatory Clerk	Conditions of Approval	Attached <input type="checkbox"/>
Date 10/17/2001	Phone (505) 599-3454	