


District I
1625 N French Dr , Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30 045 28086

OPERATOR

☐ Initial Report ☒ Final Report

| | |
|---|-----------------------------------|
| Name of Company CONOCO INC. | Contact GARY LEDBETTER |
| Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401 | Telephone No. 505-324-5837 |
| Facility Name MOORE D8 | Facility Type PRODUCTION FACILITY |

| | | |
|----------------------|----------------------|---------------------|
| Surface Owner BLM | Mineral Owner BLM | Lease No. SF-078147 |
|----------------------|----------------------|---------------------|

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|---------------|-----------------|--------------|-----------------------|-------------------------|-----------------------|-----------------------|-----------------|
| Unit Letter N | Section 26 | Township 32N | Range 12W | Feet from the 1210 | North/South Line FSL | Feet from the 1440 | East/West Line FWL | County SAN JUAN |
|------------------|---------------|-----------------|--------------|-----------------------|-------------------------|-----------------------|-----------------------|-----------------|

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release PRODUCED OIL | Volume of Release 26 BARRELS | Volume Recovered NONE |
| Source of Release ABOVE GROUND STORAGE TANK | Date and Hour of Occurrence UNKNOWN | Date and Hour of Discovery 3/28/01 5:00 PM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? DENNY FOUST, VICENTE BALDERAZ | |
| By Whom? GARY LEDBETTER | Date and Hour 3/29/01 1:30 PM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* THE PRODUCTION OIL TANK DEVELOP A 1/4" HOLE IN THE BOTTOM OF THE TANK NEXT TO THE SIDE WALL, OIL SLOWLY LEAKED FROM THE HOLE INTO THE GROUND. THE HOLE WAS CAUSED BY CORROSION. THE CONTAMINATED SOIL WILL BE REMOVED AND SAMPLES TAKEN ACCORDING TO NMOCD GUIDELINES. SOIL WILL BE LANDFARMED IF NEEDED.

Describe Area Affected and Cleanup Action Taken.*

A 10'X10' AREA INSIDE THE BERM. NONE

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|------------------------------|----------------------------------|---|
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: GARY LEDBETTER | Approved by District Supervisor: | |
| Title: SHEAR SPECIALIST | Approval Date: 4/13/01 | Expiration Date: |
| Date: 4/10/01 | Phone: 505-324-5837 | Conditions of Approval: Attached <input type="checkbox"/> |

* Attach Additional Sheets If Necessary

n DGF 0108857440