


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form



Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Merrion Oil & Gas Corporation	Contact Carl Merilatt
Address 3440 Morningstar Drive 640 Reilly Ave. - Farmington, NM	Telephone No. (505) 327-9801
Facility Name Hutt #1, San Juan County, NM	Facility Type Portable Natural Gas Compressor Facility

Surface Owner Bureau of Land Management	Mineral Owner BLM	Lease No. NM-03877
---	-----------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter E	Section 8	Township 29N	Range 11W	Feet from the 1529	North/South Line North	Feet from the 799	East/West Line West	County San Juan, NM
-------------------------	---------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	-------------------------------

NATURE OF RELEASE

Type of Release Oil Spill (VRG 330)	Volume of Release Approximately 250 gallons	Volume Recovered Approximately 250 gallons
Source of Release Aboveground Storage Tank	Date and Hour of Occurrence Between 12/30/01 - 12/31/01	Date and Hour of Discovery 12/31/01 - 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust, New Mexico Oil Conservation District, Aztec, NM	
By Whom? Cheryl Miller, EHS Coordinator, Universal Compression, Inc.	Date and Hour 01/02/02 - 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Aboveground Oil Supply Tank was vandalized. The sight glass on the tank was shot out by an unknown party, which allowed for the release of approximately 250 gallons of new motor oil (Conoco El Mar 3000 - 30W) to the surrounding ground. The release was discovered on 12/31/01 by a Universal Compression, Inc. field employee. The aboveground tank has been replaced and containment for the tank has been installed.

Describe Area Affected and Cleanup Action Taken.*

Envirotech, Inc. a spill response contractor in Farmington, New Mexico, was dispatched immediately with absorbents and spill cleanup equipment. The stained soil was removed for offsite disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Cheryl Miller	OIL CONSERVATION DIVISION	
Printed Name: CHERYL MILLER	Approved by <input type="checkbox"/> District Supervisor: Denny Foust for Frank Chavez	
Title: EHS Coordinator	Approval Date: 01/04/02	Expiration Date:
Date: 1/3/02 Phone: 326-6525	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

156F0200426953