


District I
1625 N French Dr , Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



3004530134
Release Notification and Corrective Action

OPERATOR

Initial Report ☐ Final Report ☒

Name of Company CONOCO INC.	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name FLORANCE LS 1B	Facility Type PRODUCTION FACILITY

Surface Owner BLM	Mineral Owner BLM	Lease No. NM 04241
----------------------	----------------------	--------------------

LOCATION OF RELEASE

Unit Letter G	Section 1	Township 29N	Range 10W	Feet from the 1345	North/South Line FNL	Feet from the 1960	East/West Line FWL	County SAN JUAN
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-----------------

NATURE OF RELEASE

Type of Release FRESH WATER	Volume of Release 1200 BARRELS	Volume Recovered NONE
Source of Release DRAIN VALVES ON BOTTOM OF FRAC TANKS	Date and Hour of Occurrence 9/23/01 UNKNOWN	Date and Hour of Discovery 9/24/01 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? DENNY FOUST & MARK KELLY	
By Whom? GARY LEDBETTER	Date and Hour 9/24/01 9:00 AM & 9:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

VANDALISM, DRAIN VALVES ON THREE TANKS WERE OPEN AND THE FRESH WATER WAS ALLOWED TO DRAIN OUT. NONE

Describe Area Affected and Cleanup Action Taken.*

2/3 OF THE WATER FLOWED INTO THE RESERVE PIT AND THE OTHER 1/3 RAN OFF OF LOCATION 100' INTO THE BRUSH. NONE

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary Ledbetter</i>	OIL CONSERVATION DIVISION	
Printed Name: GARY LEDBETTER	Approved by District Supervisor: <i>Denny Foust</i>	for Frank Chavez
Title: SHEAR SPECIALIST	Approval Date: <i>10/10/2001</i>	Expiration Date:
Date: <i>10/8/01</i> Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary