


30-045-08860

Inspected 10-26-59
OK Krall & HozeBudget Bureau 42-R358.3.
Approval expires 12-31-55.Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. SF 079968

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	XX
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 4, 1955

Russell
Well No. 4 is located 990 ft. from N line and 990 ft. from E line of sec. 4
NE 1/4 Section 4 29N 14W N.T.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Twin Mounds PC San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5448 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-1-55: Drilled to a total depth of 1155' DF with 5 1/2" 14 lb. csg., set at 950' DF and cemented to surface. Well permanently abandoned; hole was plugged to surface with 29 bbls. of natural drilling fluid.

Well capped and permanent monument installed.

RECEIVED

OCT 30 1959

U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company PUBCO DEVELOPMENT, INC.

Address 107 West Chaco
Aztec, New Mexico

By A. D. Brown
A. D. Brown

Title Petroleum Engineer