RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAR **03** 2010

	Sundry Notices and Reports on Wells			Bureau of Land Management Farmington Field Offica	
			5. 6.	Lease Number SF-080917 If Indian, All. or Tribe Name	
ator			7.	Unit Agreement Nam	
GTON					
ACES OIL &	GAS COMPANY LP		- 8	Well Name & Numbe	
. Address & Phone No. of Operator			υ.	Atlantic B Com 9A	
PO Box 4289, Farmington, NM 87499 (505) 326-9700			9.	API Well No.	
Location of Well, Footage, Sec., T, R, M Surf: Unit J (NWSE), 1500' FSL & 1825' FEL, Section 34, T31N, R10W, NMPM			•	30-045-22977	
			10.	Field and Pool	
			11.	Blanco PC/Blanco M County and State San Juan, NM	
		OF NOTICE, REPORT, O	THER I	DATA	
on Type of of Intent	of Action Abandonment	Change of Plans	X	Other - Name Change	
quent Report	Recompletion Plugging Casing Repair	Non-Routine Fracturing		RCVD WAR 16'10 OIL CONS. DIV.	
Abandonment	Altering Casing	Conversion to Injection		DIST. 3	
	GTON RCES OIL & one No. of Operat Farmington, NM ell, Footage, Sec., NWSE), 1500' FSI COPRIATE BOX on Type of cof Intent quent Report	GTON RCES OIL & GAS COMPANY LP one No. of Operator Farmington, NM 87499 (505) 326-9700 ell, Footage, Sec., T, R, M NWSE), 1500' FSL & 1825' FEL, Section 34 COPRIATE BOX TO INDICATE NATURE on Type of Action of Intent Abandonment Recompletion quent Report Plugging Casing Repair	GTON PCES OIL & GAS COMPANY LP One No. of Operator Farmington, NM 87499 (505) 326-9700 ell, Footage, Sec., T, R, M NWSE), 1500' FSL & 1825' FEL, Section 34, T31N, R10W, NMPM COPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT Type of Action Type of Action of Intent Abandonment Recompletion Recompletion Quent Report Plugging Casing Repair Water Shut off	GTON RCES OIL & GAS COMPANY LP 8. One No. of Operator Farmington, NM 87499 (505) 326-9700 9. ell, Footage, Sec., T, R, M 10. WSE), 1500' FSL & 1825' FEL, Section 34, T31N, R10W, NMPM 11. COPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER 19. on Type of Action of Intent Abandonment Change of Plans X Recompletion New Construction quent Report Plugging Non-Routine Fracturing — Casing Repair Water Shut off	

Property Code 6803

NMOCD