



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distrct.htm](http://emnrd.state.nm.us/ocd/District%20III/3distrct.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-31-10 Operator Burlington P.s. API #30-0 45-28563
Property Name San Juan 3294 SLD Well No. 5 Location: Unit A Section 18 Township 31 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 394 Intermediate N/A Casing Vac Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		Vac		
10 min	0				
15 min	0				
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	RCVD MAR 31 '10
Gas & Water	OIL CONS. DIV.
Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

1 minute to blow down - gradually opened

Vacume Squeeze needs to be put on Casing

By Alan Errett ALAN ERRETT Witness Monica Kuehling

SPECIALIST

(Position)

E-mail address _____