



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/20/10 Operator Energen Resources API # 3003906389

Property Name JICARILLA 98 2 Location: Unit A Section 19 Township 26 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 140 Intermediate Casing 175 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	175				Steady Flow	
10 minutes	0	175				Surges	
15 minutes	0	175				Down to Nothing	
20 minutes						No Flow	X
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	175				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

By  Witness
Lease operator
(Position)

