



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-5-10 Operator Devon API #30-0 3907802
Property Name NcBu 475 Well No. 413 Location: Unit 20 Section 20 Township 30N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 12 Intermediate 0 Casing 31 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	30	0	31
10 min	0	0	30	0	30
15 min	0	0	30	0	30
20 min	0	0	30	0	30
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
<u>Slight Flow</u>	
Steady Flow <u>Steady Flow</u>	
Surges <u>-</u>	<u>-</u>
Down to Nothing	<u>✓</u>
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Int. Casing Slight Gas Press. Blew Down In M.
Braden Head Blew Down 3 min. very slight Flow

By John W. [Signature]

(Position)

Witness John [Signature]

E-mail address

