



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3distric.htm](http://emnrd.state.nm.us/ocd/District%20III3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-11-10 Operator Devon API #30-0 3907880
Property Name NEBU Well No. 8 Location: Unit Section 10 Township 30N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 31 Intermediate Casing 48 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	-	48		
10 min	0	-	48		
15 min	0	-	48		
20 min	0	-	48		
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing	✓	
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Jon A. Winters
Tester
(Position)

Witness ✓ [Signature] - Devon

E-mail address

