



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-18-10 Operator Devon API #30-0 390 7897
Property Name NEBU Well No 27 Location: Unit 8 Section 8 Township 30^N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate 70 Casing 52 Bradenhead 29

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	52	0	52
10 min	1	0	52	0	52
15 min	1	0	52	0	52
20 min	1	0	52	0	52
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		✓
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Braden Head slight Gas on valve

By

Jared Winter
Tester

(Position)

Witness

Mike Long - Devon

E-mail address _____

