



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-25-10 Operator DEVON API #30-0 3921408
Property Name NEBU Well No. 224 Location: Unit 34 Township 31^N Range 7W
Well Status(Shut-In or Producing) Initial PSI: Tubing 23 Intermediate 120 Casing 41 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	.2	41	.2	41
10 min	0	5	41	5	41
15 min	0	10	41	10	41
20 min	0	11	41	11	41
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	✓
Surges	✓
Down to Nothing	
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE .2

REMARKS: Interm. Took 10mins. To Blowdown, Surged APP. Every
1min Steady Flow

By J. Winters
(Position)

Witness [Signature]

E-mail address _____

