NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-17-10 Operator Devon API #30-0 3921723

Property Name NEBU Well No. 44A Location: Unit ___ Section 4 Township 30 N Range 7W

Well Status(Shut-In or (Producing)) Initial PSI: Tubing 61 ~~Intermediate~~ ___ Casing 55 Bradenhead 53

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	~~Int~~	Csg	INTERM Int	Csg
TIME 5 min	1	–	55		
10 min	2	–	55		
15 min	3	–	55		
20 min	3	–	55		
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3 INTERMEDIATE ___

RECEIVED JUN 2010 OIL CONS. DIV. DIST. 3

REMARKS: Slight Gas Flow on Bradenhead

By [signature] Tester (Position)

Witness [signature] - Devon

E-mail address _____