



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3distric.htm](http://emmr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 5-10-10 Operator Devon API #30-0 3927301
Property Name NEBU Well No. 407A Location: Unit I Section 21 Township 30N Range 28E
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate - Casing 4 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>	<u>-</u>	<u>4</u>		
10 min	<u>5</u>	<u>-</u>	<u>4</u>		
15 min	<u>6</u>	<u>-</u>	<u>3.8</u>		
20 min	<u>6</u>	<u>-</u>	<u>4</u>		
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow	☒	
Surges		
Down to Nothing		
Nothing		
Gas	☒	
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1 INTERMEDIATE _____

REMARKS:

Aug upbl. Verify BH Blew steady 1 PSI. Flow shut in
15 min. Press To 6 PSI.

By

Paul Winters

(Position)

Witness

[Signature]

E-mail address _____