NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test _5/20/10_   **Operator** Energen Resources   **API #** 3003927312

Property Name JICARILLA 98 12A   **Location:** Unit N   Section 18   Township 26   Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing _85_ Intermediate _____ Casing _85_ Bradenhead _0_

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	0	85				Steady Flow		
10 minutes	0	85				Surges		
15 minutes	0	85				Down to Nothing		
20 minutes						No Flow	X	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	85				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in   Bradenhead _0_   Intermediat _____

REMARKS:
_____
_____
_____
_____

By _____   Witness _____
Lease operator
(Position)

NMOCD Test Area: C   471