



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-10 Operator Energen Resources API # 3003905615

Property Name JICARILLA H 11 Location: Unit N Section 6 Township 24 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 78 Intermediate Casing 205 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ø	205				Steady Flow		
10 minutes	Ø	205				Surges		
15 minutes	Ø	205				Down to Nothing		
20 minutes						No Flow	X	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	Ø	205				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead Ø Intermediate

REMARKS: NOTHING ON BRADENHEAD.



By [Signature] Witness

LEASE OPERATOR

(Position)