

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

			(Oubilli	t z copies to at	ove addie	33,		
Date of Test 5-18-10		Operator —	Energen Resources		ces /	API#	3003905801	
Property Name	e	JICARILLA 67 10		Location: Unit M Section 30		Section 30 T	ownship 2	25 Range 5
		(Well Name	and Number)					
Pressure (Shu	ut-in or Proc	ducing)	Tubing _	IZO Interme	diate	Casing	<b>39</b> Brade	enhead TSTM
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUTES	S EACH
	Bradenhead			Interme	diate		Bradanha	ad Intermediate
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	
5 minutes	TSTW	139	Monto	Biowdown	MOUNTO	Steady Flow	×	•
10 minutes	T5TM	139				Surges		
15 minutes	TSTM	139				Down to Nothing		
20 minutes	TSTU	137				No Flow		
25 minutes	7374	134				Gas	<u> </u>	
30 minutes	15TM	139				Gas and Water		
5 minute SI	TSTM	139				Water		02031-72
Somminutes  5 minute SI  TSTM 139  If bradenhead flowed water, check all of the descriptions that apply below:  Clear Fresh Salty Sulfur Black  5 Minute Shut-in Bradenhead TSTM Intermediat  REMARKS:  BANGUHAN HAD SOFT STRADY FLOW. TSTM.								
ву <u>£</u>	_		<b>&gt;</b>		tness	W. TSTM		
<u></u>	ASE C	PRRKT	TOR	***************************************				

(Position)