

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

			(0			,			
Date of Test	5/18	110	Operator 	Energ	Energen Resources			# 3003906175	
Property Name		RUDI	DOCK 2	Location: Unit D Section 3			ownship 25	Range 3	
		(Well Name	and Number)						
Pressure (Shu	t-in or Pro	ducing)	Tubing 👱	105 Interme	diate	Casing	95 Bradenh	ead <u>757/</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
Γ	Bradenhead			Interme	diate		Bradenhead	Intermediate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	0	105				Steady Flow			
10 minutes	0	105				Surges			
15 minutes	0	105				Down to Nothing			
20 minutes						No Flow			
25 minutes			- · · · · · · · · · · · · · · · · · · ·			Gas			
30 minutes	2				<del></del>	Gas and Water			
5 minute SI	TSTM	105				Water			
Clear  5 Minute Shu	F	resh	Sali	escriptions than	Sulfur		OIT CONS. OIT CO	TEIVED ON DIST. 8 SOUTH OF THE PARTY OF THE	
ву <i>Ат</i> 50.									

(Position)