



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/21/2010 Operator Energen Resources API # 3003906882

Property Name JICARILLA 95 4 Location: Unit M Section 26 Township 27 Range 3

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 29 Intermediate NA Casing 100 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>0</u>	<u>100</u>										
10 minutes	<u>0</u>	<u>100</u>										
15 minutes	<u>0</u>	<u>100</u>						☒				
20 minutes												
25 minutes												
30 minutes												
5 minute SI	<u>0</u>	<u>108</u>										

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

blew down right away

By Ed Mauer

Witness _____

(Position)