



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-10 Operator Energen Resources API # 3003922886

Property Name JICARILLA L 10 Location: Unit D Section 9 Township 24 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 100 Intermediate Casing 162 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ø	160				Steady Flow		
10 minutes	Ø	150				Surges		
15 minutes	Ø	150				Down to Nothing		
20 minutes						No Flow	X	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	Ø	148				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead Ø Intermediat

REMARKS:

NOTHING ON BRADENHEAD, WELL FLOWING.

By

[Signature]

Witness

LEASE OPERATOR

(Position)

