



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003923313

Property Name MCCRODEN 5 Location: Unit A Section 9 Township 25 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 20 Intermediate Casing 20 Bradenhead 7.5Tm

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>20</u>					
10 minutes	<u>0</u>	<u>20</u>					
15 minutes	<u>0</u>	<u>20</u>					
20 minutes							
25 minutes							
30 minutes							
5 minute SI	<u>7.5Tm</u>	<u>20</u>					
						Steady Flow	
						Surges	
						Down to Nothing	<u>X</u>
						No Flow	
						Gas	<u>X</u>
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 7.5Tm Intermediate

REMARKS:

well flowing

By Armando Chacon

Witness

sr. lease operator

(Position)

