



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003924120

Property Name MCCRODEN A 9 Location: Unit A Section 9 Township 25 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 0 Intermediate 0 Casing 25 Bradenhead TSTM

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	25				Steady Flow	
10 minutes	0	25				Surges	
15 minutes	0	25				Down to Nothing	X
20 minutes						No Flow	
25 minutes						Gas	X
30 minutes						Gas and Water	
5 minute SI	TSTM	25				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_

5 Minute Shut-in Bradenhead TSTM Intermediate \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Amado Chavez Witness \_\_\_\_\_  
sen. lease operator  
(Position)

