



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/2010 Operator Energen Resources API # 3003926856

Property Name JICARILLA 94 2B Location: Unit N Section 27 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 90 Intermediate N/A Casing 110 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>110</u>				Steady Flow		
10 minutes	<u>0</u>	<u>110</u>				Surges		
15 minutes	<u>0</u>	<u>110</u>				Down to Nothing		
20 minutes						No Flow	☒	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	<u>0</u>	<u>110</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

By Ed Mauer Witness _____
Pumper
(Position)

