



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 01/13/09 Operator BP America Production Company API # 3004532735

Property Name MUDGE GC B 001M-MV/DK Location: Unit P Section 11 Township 31 Range 11
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 25 Intermediate 520 Casing 78 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	78	520	120	78	Steady Flow	X
10 minutes	0	78	520	25	78	Surges	
15 minutes	0	78	520	4	78	Down to Nothing	X
20 minutes				2	78	No Flow	
25 minutes				0.5	78	Gas	X
30 minutes				0.5	78	Gas and Water	
5 minute SI	0.5			4		Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

RCVD JUN 24 '10
OIL CONS. DIV.
DIST. 3

REMARKS:

Bradenhead pressure down to nothing in 1 second, puff after 5 min SI. Intermediate pressure had good blow at 30 minute interval. 1" valves. NMOCD requested retest.

By Ray Ledesma Witness Monica Kuehling

NMOCD Test Area: A