



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emurrd.state.nm.us/ocd/District 3/district.htm](http://emurrd.state.nm.us/ocd/District%203/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-14-10 Operator ELM RIDGE EXP. API # 30-039-23720

Property Name LEESON Well No. 1 Location: Unit K Section 27 Township 25 Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 110 Intermediate Casing 110 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>110</u>			
10 min	<u>0</u>		<u>110</u>			
15 min	<u>0</u>		<u>110</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:



By Don Shipley

Witness

pumper
(Position)

E-mail address