



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-26-10 Operator Energen Resources API # 3003924411

Property Name CARRACAS UNIT 35 A 8 Location: Unit H Section 35 Township 32 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 215 Intermediate N/A Casing 95 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	95	N/A	N/A	N/A	Steady Flow	N/A
10 minutes	0	95				Surges	
15 minutes	0	95				Down to Nothing	
20 minutes	0	95				No Flow	X
25 minutes	0	95				Gas	
30 minutes	0	95				Gas and Water	
5 minute SI	0	195				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Jon Hardy  
Lease Operator

(Position)

Witness \_\_\_\_\_

