



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-26-10 Operator Energen Resources API # 3003926477

Property Name CARRACAS 36 A 5 Location: Unit E Section 36 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 60 Intermediate N/A Casing 82 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	62	N/A	N/A	N/A	Steady Flow		N/A
10 minutes	0	62				Surges		
15 minutes	0	62				Down to Nothing		
20 minutes	0	62				No Flow		
25 minutes	0	62				Gas		
30 minutes	0	62				Gas and Water		
5 minute SI	0	95				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Jon Lark
Lease Operator
(Position)

Witness _____

