



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/4/10 Operator: Elm Ridge Exploration CO LLC API #30-039-<sup>43</sup>20029

Property Name Scarm 11a360 Well No. 1 Location: Unit C Section 1 Township 2N Range 3W

Well Status (Shut-In or Producing) Tubing 50 Intermediate      Casing      Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes <u>0</u>				Steady Flow <u>    </u>	
10 minutes <u>0</u>				Surges <u>    </u>	
15 minutes <u>0</u>				Down to Nothing <u>    </u>	
20 minutes <u>    </u>				Nothing <u>✓</u>	
25 minutes <u>    </u>				Gas <u>    </u>	
30 minutes <u>    </u>				Gas & Water <u>    </u>	
				Water <u>    </u>	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE     

REMARKS:

Slim hole



By     

Witness     

Pumper  
(Position)

Sub Dur

E-mail address