



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-15-10 Operator Burlington API #30-0 39-23501
Property Name San Juan 30-6 Well No. 1124 Location: Unit 26 Section 30 Township 30 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 299 Intermediate N/A Casing 655 Bradenhead 32

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
5 min			655			
10 min			654			
15 min			652			
20 min			652			
25 min			651			
30 min			651			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

OIL CONS. DIV.

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Blowing through 1/2" valve

15 min → vapor after five minutes

RCVD JUL 16 '10

By [Signature]
SWD SUPERVISOR
(Position)

Witness [Signature]

E-mail address _____