



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 7-16-10 Operator Burlington Res. API # 30-0 39-23501

Property Name San Juan 30-664 Well # 1124 Location: Unit Sec 26 Twn 30 Rge 6

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. 118 Tbg. SI Pres. Max. Inj. Pres.
Bradenhead Pres. 0 Tbg. Inj. Pres.
Tubing Pres. 525
Int. Casing Pres. N/A

DIST. 3

Pressured annulus up to 360 psi. for 30 mins. Test passed/failed CONS. DIV.

REMARKS

RCVD JUL 16 '10

-Packer set 8172

602 Perf- 8221

Hose was in down last 15 minutes of test

By Patricia Steward
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

SLWD SUPERVISOR
(Position)

Revised 02-11-02

