

RECEIVED

JUL 20 2010

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

Farmington Field Office
Bureau of Land Management

1. Type of Well Gas	5. Lease Number NOO-C-14-20-5369
2. Name of Operator <i>Pro Management</i> % Max D. Webb	6. If Indian, All. or Tribe Name Navajo
3. Address & Phone No. of Operator PO Box 190, Farmington, NM 87499	7. Unit Agreement Name
Location of Well, Footage, Sec., T, R, M 1730' FNL & 975' FWL, Section 4, T-25-N, R-12-W,	8. Well Name & Number Navajo 4 #1
	9. API Well No. 30-045-22774
	10. Field and Pool Nipp Pictured Cliffs
	11. County & State San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☒ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☐ Other -

13. Describe Proposed or Completed Operations

This well was plugged and abandoned per the attached report on 7/13/10.

RCVD JUL 22 '10
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor Date 7/13/10

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

JUL 21 2010

NMOCD

FARMINGTON FIELD OFFICE

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 * fax: 505-325-1211

Max D. Webb

July 13, 2010

Navajo 4 #1

Page 1 of 1

1730' FNL & 975' FWL, Section 4, T-25-N, R-12-W

San Juan Country, NM

Lease Number: NOO-C-14-20-5369

API#30-045-22774

Plug and Abandonment Report

Plugging Summary:

07/09/10 MOL and RU cementing equipment. Connect pump tee to casing hose. Load casing with 13 bbls of water. Establish rate 2 bpm at 200 PSI.

Plug #1 spot 72 sxs Class B cement (84.96 cf) inside casing from 1107 to surface to isolate the Pictured Cliffs interval and cover the Fruitland top. Note: at 40 sxs, pumped pressure up from less than 50 PSI to 500 PSI, then circulation began out the annulus. Continue pumping until good cement circulated out the annulus to surface.

SI well and WOC. Found cement down 25' in the casing and down 7' in the annulus.

Top off casing and annulus with and install P&A marker with 10 sxs Class B cement. Fill in cellar with soil.

RD and MOL.

Wanda Weatherford, BLM representative, was on location.