



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test: 2-12 Operator: RESOURCE DEVELOPMENT TECHNOLOGY, LLC API #30-039-05161

Property Name: YARBOROUGH FED Well No. 1 Location: Unit J Section 3 Township 23N Range 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing: 26 Intermediate: 0 Casing: 26 Bradenhead: 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH	Int	Csg	Int	Csg		Flowed	Flowed
5 Min	<u>0</u>	<u>0</u>	<u>26</u>	NA	NA	Steady Flow		
10 Min	<u>0</u>	<u>0</u>	<u>26</u>	NA	NA	Surges		
15 Min	<u>0</u>	<u>0</u>	<u>26</u>	NA	NA	Down to Nothing		
20 Min	<u>0</u>	<u>0</u>	<u>26</u>	NA	NA	Nothing	<u>X</u>	
25 Min	<u>0</u>	<u>0</u>	<u>26</u>	NA	NA	Gas		
30 Min	<u>0</u>	<u>0</u>	<u>26</u>	NA	NA	Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Ramping Well - lost shut in BH

By: Art Sullivan Witness

Lease Operator -- Pumper
(Position)

E-mail address: lizard3s@wildblue.net

