

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5-0	5 -20 - 2010 Operator			Energen Resources			3003905447	
Property Name	•	LINDRITH UNIT 32			Location: Unit K Section 16		ownship 24	Range 3	
		(Weil Name	and Number)						
Pressure (Shu	ıt-in or Proc	ducing)	Tubing	15_ Interme	diate	Casing <u>//</u>	A Bradenh	ead <u>Ø</u>	
OPEN	BRADENH	EAD AND	INTERMEDIAT	TE TO ATMOSE	PHERE IND	DIVIDUALLY FOR	15 MINUTES E	ACH	
	Bradenhead			Interme	diate	Bradenhead Intermediate			
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes		NA	Worker	- Biowadwii	Monitor	Steady Flow			
10 minutes	<u>(6</u>	JV 7F				Surges			
15 minutes	8					Down to Nothing			
20 minutes						No Flow	X		
25 minutes						Gas	,		
30 minutes						Gas and Water			
5 minute SI	8			-		Water			
If bradenhes Clear 5 Minute Sh	F	vater, che resh _ radenhea	Salt		t apply bel	<u>ow:</u> Bla	RECE DIL CONS. I	2010 11273 DIV. DIST. 3 2	
By Juli	A	ease (Doeator	Wi	tness				

(Position)