

5053279207

Benson-Montin-Greer

03:37:34 p.m.

07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(808) 334-6178 FAX: (808) 334-6170
<http://enmrd.state.nm.us/ocod/District11/ASDdistricts.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/10 Operator Benson Montin Greer API #30-0 39-06051Property Name COU Well No. 4 Location: Unit P Section 11 Township 25N Range 1WWell Status (Shut-In or Producing) Initial PSI: Tubing 76 Intermediate 114 Casing 110 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>110</u>		
10 min	<u>0</u>		<u>112</u>		
15 min	<u>0</u>		<u>115</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

Down to nothing in 26 sec.

By

Ben L. Gonzales

Witness _____

(Position)

E-mail address _____

