

5053279207

Benson-Montlin-Creer

03:37:34 p.m.

07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://ohmnr.state.nm.us/ood/District/USDistrict.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/22/10 Operator Benson Montlin Creer API #30-0 39-06769Property Name EPCW4 Well No. 9 Location: Unit H Section 30 Township 27N Range 1EWell Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead			INTERMEDIATE	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By Bent L. Young

Witness _____

(Position)

E-mail address _____

