

5053279207

Benson-Montin-Greer

03:37:34 p.m. 07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-8170
<http://omnr.state.nm.us/ocd/District/1000RioBrazos.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/22/10 Operator Benson Montin Greer API #30-0 39-06863Property Name Elmua Well No. 12 Location: Unit 4 Section 19 Township 27N Range 1EWell Status (Shut-In or Producing) Initial PSI: Tubing 76 Intermediate N/A Casing 34 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>K</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Ben L. G. Greer

Witness _____

(Position)

E-mail address _____

