

5053279207

Benson-Montin-Greer

03:37:34 p.m.

07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 554-0170 FAX: (505) 554-0170
<http://emrmd.state.nm.us/aztec/district/103adistare.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/10 Operator Benson Montin Greer API #30-0 39-08144Property Name COU Well No. 10 Location: Unit 0 Section 33 Township 26N Range 1WWell Status (Shut-In or Producing) Initial PSI: Tubing 40 Intermediate 1/4 Casing 30 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		30		
10 min	0		30		
15 min	0		30		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

Steady Flow

Surges


Down to Nothing X

Nothing

Gas X

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

Down to Nothing in 1 min.

By

Benson Montin Greer

Witness _____

(Position)

E-mail address _____